



DOP: 3469-0145-085-000

### Technical Details | Technische Daten

**Manufacturing process** | Herstellungsart

**Frontside structure** | Oberseitengestaltung

**Color** | Farbgestaltung

**Pile material** | Material der Nutzschicht

**Primary backing** | Träger- / Grundgewebe

**Secondary backing** | Rückenausstattung

**Pile weight** | Poleinsatzgewicht

**Total weight** | Gesamtgewicht

**Pile height** | Polhöhe

**Total thickness** | Gesamtdicke

**Number of knots** | Noppenzahl

**Width** | Breite

DIN ISO 2424 **tufted** | getuftet 1/10"

DIN ISO 2424 **Cut pile – saxony** | Schnittpol Saxony Velours

DIN ISO 2424 **Chromojet print** | Chromojet Druck

**Wool 80 % - PA 20 %**

DIN ISO 2424 **PES Non Woven** / PES Bändchen

DIN ISO 2424 **Felt backing** / Filz Rücken

DIN ISO 2424 approx. | ca. **1400 g/m<sup>2</sup>**

ISO 8543 approx. | ca. **3252 g/m<sup>2</sup>**

ISO 1766 approx. | ca. **6,4 mm**

ISO 1765 approx. | ca. **10,5 mm**

ISO 1763 approx. | ca. **177165 /m<sup>2</sup>**

DIN 3018 approx. | ca. **395 cm**

### Functional properties | Funktionseigenschaften

**Wear classification** | Beanspruchungsklasse

EN 1307:2019

**23/32**

**Comfort rating** | Komfortklasse

EN 1307:2019

**LC 4**

### Physical properties | Bauphysikalische Eigenschaften

**Fire rating** | Brandverhalten

DIN EN 13501-1

**Bfl-s1**

### Fastnesses | Echtheiten

**Colour fastness to light** | Lichtechtheit

EN ISO 105-B02:2013

**> 6**

**Colour fastness to water** | Wasserechtheit

DIN EN ISO 105 E01:2013

**5**

**Rubbing fastness dry/wet** | Reibechtheit trocken/nass

DIN EN ISO 105 X12:2002

**5 / 5**



These details are approximate. Complete specification details and associated certificates together with tolerances applying to the above can be provided upon request. We reserve the right to alter specifications without notice. Due to method of manufacture, perfect pattern and/or colour matching cannot be guaranteed. In cut pile carpet, shading/pile reversal might occur without affecting overall quality and suitability. Shading/pile reversal will not be considered as a manufacturing fault and will not affect the durability of the carpet.

Rev.: 006/10.2023